Model	Unit	Transmission Ratio	Smallest Pointer 1 Revolution	No of Teeth	Pulses Per 1 Galon	Qmax gal	Frequency No of pulses in 1 second at Qmax
BM 1 1/2"	GAL	18.78	1	4	75.12	88	110.176
BM 2"	GAL	11.7	1	4	46.8	132	102.960
BM 3"	GAL	4.871	1	4	19.484	352	114.306
BM 4"	GAL	17.66	10	4	7.064	528	62.163
BM 6"	GAL	15.9	10	4	6.36	1320	139.920
BM 8"	GAL	3.151	10	4	1.2604	2376	49.912