
## **PVC INSPECTION CHAMBERS SDR 35**

Conform to ASTM D3034



ITEM	SIZE AND DESCRIPTION	PART NUMBER	LIST PRICE EACH
SINGLE SERVICE INSPECTION CHAMBER	UNPLUGGED LESS FLAP  4" x 4"  6" x 6"  UNPLUGGED WITH FLAP  4" x 4"  6" x 6"  PLUGGED  4" x 4"  6" x 6"	V70104 V70106 V70204 V70206 V70304 V70306	166.38 232.93 186.34 266.20 199.65 286.17
REDUCING SINGLE SERVICE INSPECTION CHAMBER	UNPLUGGED LESS FLAP 6" x 4"  UNPLUGGED WITH FLAP 6" x 4"  PLUGGED 6" x 4"	V70106-4 V70206-4 V70306-4	279.51 299.48 308.79
	UNPLUGGED  4" x 4" x 4" DOUBLE SERVICE  6" x 6" x 6" DOUBLE SERVICE  6" x 4" x 4" DOUBLE SERVICE	V80404 V80406 V80406-4	532.40 572.33 559.02
DOUBLE SERVICE INSPECTION CHAMBER  NOTE: DOUBLE IC'S ARE NOT FLAP CAPABLE	PLUGGED  4" x 4" x 4" DOUBLE SERVICE  6" x 6" x 6" DOUBLE SERVICE  6" x 4" x 4" DOUBLE SERVICE	V80504 V80506 V80506-4	578.99 638.88 618.92
LID & COLLAR FOR 8" RISER	8" COLLAR 8" LOCKING COLLAR 8" LID 8" LOCKING LID 8" SOLVENT WELD CAP WITH BOLT 8" GASKETED CAP WITH BOLT	V20308 V20408 V20508 V20608 V20708 V20808	39.93 53.24 53.24 79.86 59.90 63.89









## **PVC INSPECTION CHAMBERS SDR 35**

Conforn to ASTM D3034



ITEM	SIZE AND	PART	LIST PRICE
	Description	Number	EACH
INSPECTION CHAMBER FLAP WITH HOOK	4"	V30004	15.97
	6"	V30006	23.96
PULLERS AND HOOKS FLAP AND LID TOOLS	10' ROD WITH HANDLE 5' ROD EXTENSION PLUG PULLER HOOK FLAP INSTALL/REMOVE HOOK FLAP HOOK FLAP TAB REMOVAL TOOL LOCKING LID WRENCH TOOL	V4010 V4005 V4000 V4100 V4200 V4300 V4400	266.20 93.17 159.72 106.48 66.65 46.59 26.62
DRIVEWAY BOX FOR 8" SDR 35 RISERS	CAST IRON DRIVEWAY BOX WITH BOLT ON LID	V5000	299.48

SOME ITEMS ARE SPECIAL ORDER AND MAY NOT QUALIFY FOR PREPAID FREIGHT. SPECIAL ORDER ITEMS ARE NON-CANCELABLE.

INSPECTION CHAMBERS ARE ALSO AVAILABLE IN DWV



